

MONUMENT RECORD


Corner I.D. #

H-4

STATE OF INDIANA - COUNTY OF MONROE

Section Five (5), Township 10 North, Range 1 West

Monument Description & Remarks: Set monument with brass IDNR cap at the
SE Corner of NW 1/4 of SE 1/4, 7/31/87. (Hub found flush w/ground 7/25/87.)



State of Indiana
 County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; and the above data is given under my hand and seal this 7th day of October, 1993 A.D.

Space
 Reserved For
 Recording
 Officer

Indiana Registered Land Surveyor No. _____ or

Morgan-Monroe State Forest
 United States Government Agency

David C. Vadas, Timber Specialist

Title

Field Book:

n/a

Page:

n/a

July 21, 1987, Jim Allen, Darrell Breedlove, and I set a "trial" monument with brass cap at the NW corner, E $\frac{1}{4}$, NW $\frac{1}{4}$, SW $\frac{1}{4}$, SEC 5.

David Vadas, Timber Specialist

16. On July 24, 1987, I reflagged the survey line of Bob Vollmer along the Horace Baugh property. The center of the section had been marked by a rebar (5/8") in a pile of rocks in the center of the stream. It was witnessed as follows:

PK nail	237°	at	12.22'	to a	16.3"	REO	2:40 PM	5
PK nail	138°	at	13.84'	to a	05.7"	BLB	90% clear	
PK nail	053°	at	15.17'	to a	04.3"	REE	Hot & humid	

Five steel fence posts were found along the line against Mr. Baugh. Three were closest to the center section rebar while 2 SFP were found by the old logging road on top of the ridge. The latter 2 SFP were found to have been dug up, but seemed to be set in the original holes (still standing). Also, the E line of the NW $\frac{1}{4}$, SE $\frac{1}{4}$ was reflagged and the adjustment was 4 paces E in 254 paces. Approx. $\frac{1}{2}$ of the N line was painted in and posted. The old paint line still needs to be painted over.

David Vadas, Timber Specialist

17. On July 25, 1987, I painted in approximately $\frac{1}{2}$ of the E line flagged in on July 24, 1987 (the south $\frac{1}{2}$ of the E line of NW $\frac{1}{4}$, SE $\frac{1}{4}$). Also, the SE corner of the NW $\frac{1}{4}$, SE $\frac{1}{4}$ was witnessed as follows:

PK nail	166°	at	6.27'	to a	15.8"	WHO	Hub flush with ground	
PK nail	228°	at	6.25'	to a	02.6"	SUM	2:45 PM Cloudy	90%
PK nail	325°	at	8.65'	to a	03.6"	DOG		

David Vadas, Timber Specialist

S 14° E ✓

S 48° W ✓

N 38° W ✓

See #19

July 28, 1987, I flagged in and painted the N line of the NE $\frac{1}{4}$, SW $\frac{1}{4}$ (Grieco property line). Wooden fence stakes were observed at points of 80 paces, 109.5 p. and 141.5 p. E of the NW corner (iron pipe). The post 141.5 p. E seemed to be the point where the Grieco encroachment (pasture fence) occurred. The Grieco encroachment covered from pace 141.5 E to pace 233.5 E and was about 30' in width at pace 233.5. The line was posted at the fence stakes and on the corners. The first part of the Grieco fence appeared to be on line.

David C. Vadas
David Vadas, Timber Specialist

19. On July 31, 1987, two Summer Youth employees and I set the following monuments along with brass IDNR caps: The SW corner of the E $\frac{1}{4}$, NW $\frac{1}{4}$, SW $\frac{1}{4}$; The NE & SE corners of the NW $\frac{1}{4}$, SE $\frac{1}{4}$; (all in SEC 5).

David C. Vadas
David Vadas, Timber Specialist

20. On August 5, 1987, while grading & waterbarring portions of the new road. I flagged in the following lines following the Vollmer survey: N line of SE $\frac{1}{4}$, SE $\frac{1}{4}$ and the N line of the 5 acre piece in the NE $\frac{1}{4}$, SE $\frac{1}{4}$ all in SEC 5. The N line of the 5 acre piece evidently did not have corners set from the Vollmer survey that was completed in July, 1987.

David C. Vadas
David Vadas, Timber Specialist

21. On August 6, 1987, I painted in and posted the following lines: N line of SE $\frac{1}{4}$, SE $\frac{1}{4}$; N line of NW $\frac{1}{4}$, SE $\frac{1}{4}$ (E $\frac{1}{2}$); E line of NW $\frac{1}{4}$, SE $\frac{1}{4}$ (N $\frac{1}{2}$). The SW corner of the 5 acre piece in the SE corner of the NE $\frac{1}{4}$, SE $\frac{1}{4}$ was witnessed as follows:

Pk nail 165° at 19.60' to a 08.90" WHO
Pk nail 217° at 15.24' to a 18.00" REO
Pk nail 263° at 15.90' to a 06.00" AMB (sign)

Hub flush with ground
11:30 AM, clear, 85°

2

green stakes. I then went $\frac{1}{4}$ mile to the east to see if there was any marked $\frac{1}{4}$ - $\frac{1}{4}$ corner (SE corner of same $\frac{1}{4}$ - $\frac{1}{4}$). No evidence was found there either. A boundary sign was found in the drainage, but was probably moved being far away from the supposed true line. Orange boundary paint was placed along the adjusted line and boundary signs were placed at turning corners.

David C. Vadas
David Vadas, Timber Specialist

4. On February 3, 1987, I painted in the lines following: the east line of the $W\frac{1}{2}$, $NE\frac{1}{4}$, $NE\frac{1}{4}$, SEC 5 and the south line of the $W\frac{1}{2}$, $NE\frac{1}{4}$, $NE\frac{1}{4}$, SEC 5. Four rebar stakes were witnessed as follows:

The NE corner, $W\frac{1}{2}$, $NE\frac{1}{4}$, $NE\frac{1}{4}$
10:55 A.M. Cloudy, calm 38°

PK nail 318' 10.30' to a 05.2" AMB Lies in center of old road bed
PK nail 051' 12.75' to a 10.2" WHA
PK nail 176' 12.85' to a 16.8" YEP. Surveyed '86 D. Roland?
342-8175

*N 42° W
N 50° E
S 04° E*

Rebar 240' (survey pt.) S of NE corner, $W\frac{1}{2}$, $NE\frac{1}{4}$, $NE\frac{1}{4}$ 12:42 PM

PK nail 049' 18.30' to a 11.0" YEP
PK nail 102' 05.50' to a 07.3" SAS
PK nail 180' 10.35' to a 07.9" SAS (line tree)

Rebar at SE corner $W\frac{1}{2}$, $NE\frac{1}{4}$, $NE\frac{1}{4}$ 1:48 PM

PK nail 027' 06.2' to a 11.7" REO
PK nail 159' 15.6' to a 17.2" AMB
PK nail 233' 25.0' to a 10.7" BLO

Threaded Surveyor RIN at SW corner $W\frac{1}{2}$, $NE\frac{1}{4}$, $NE\frac{1}{4}$ 3:10 PM

PK nail 327' 12.80' to a 28.0" YEP
PK nail 256' 17.50' to a 23.5" BLW (double)
PK nail 110' 14.55' to a 09.8" SAS

Also, I used the staff compass to find the SE corner, $NE\frac{1}{4}$, $NE\frac{1}{4}$ by taking an easterly line off the SE corner, $W\frac{1}{2}$, $NE\frac{1}{4}$, $NE\frac{1}{4}$.

Boundary signs placed at turning corners and along the road.

David C. Vadas
David Vadas, Timber Specialist